




**Test Site:** Atlanta Georgia – 10<sup>th</sup> Street in front of MARTA Station.

**Characteristics:** Heavy traffic, in tire line and buses departing from the MARTA station front LH tire turns on manhole cover.



The test site is a sewer using UGT 40 inch product. The site was installed May of 2008. The hole was inspected on July 15<sup>th</sup> of 2009. The following shows the test results.



No deterioration of surrounding pavement.



No buckling or compression setting or fatigue.



Inflow only from cover, notice the rust



**Conclusion**



The test hole shows no deterioration on one of the most traveled street in Atlanta. The test site also shows how UGT products integrate with existing structures. UGT is anticipating GA DOT approval in August of 2009